

Building	Site Name	Site Code	Year / Season
1	Port Louis	PL	2019
Ward number W3	Block number 1	Elevation	Measure, Length
Building/Structure Type Hospital	Building status Disturbed/Restored	Types of analysis Photo	
Visibility Good	Preservation Status Good	Photoplan 3d	
Distinction Parameters Morphology / Shape	Bdg.Type Type G+1	Drone Stratigrafic Analysis	
Neighbourhood Hopital Militaire	Address Quay Street	Texture Photo Sample Construction Materials	
Openings Notes		Stone Agamasse	
Roof Material Agamasse	Roof Type Flat roof	Roof Notes	
Siding Material Stone	Siding Notes Covered with recent plaster/paint		
Dating Elements	The construction started in 1735 it was completed in 1740	Proposed chronology 1735/1740, construction	

Photo, Sketch or Audio Comment

Description



Block B of the Former Military Hospital in Port Louis, rectangular shape building, 2 stories, main entrance on the south side, other 5 doors (part of them are added in a second phase) 4 windows at the ground floor, 14 windows at 1st floor, flat roof in "agamasse". Coral stones and basalt stones framing doors/windows.

Building	Site Name	Site Code	Year / Season
2	Port Louis	PL	2019
Ward number W6	Block number 35	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Adequate		Photoplan 3d
Distinction Parameters Building technique	Bdg.Type Type G+2		
Neighbourhood West Chinatown	Address David Street		Construction Materials
Openings Notes		Stone Concrete	
Roof Material Concrete	Roof Type Flat roof	Roof Notes Not visible	
Siding Material Stone	Siding Notes Original stone sidings, 1st floor recently repainted		
Dating Elements	Proposed chronology	Probably late French	
Photo, Sketch or Audio Comment			Description



Store or store/office originally type G+1 with a flat roof, now restored with a second store. It has 3 doors on David St. and 2 doors on Sun Yat Sen St.. First floor has 2 windows and 1 door on David street, and 2 windows on Sun Yat. Probably this is due the the insertion of a inner staircase. First floor was recently repainted but the original stone pattern is visible. The aeration system is embedded on the doors on the ground floor, while in the first floor is done with new aereation openings. The original building had a probably wooden terrace, now replaced with a concrete one.

Building	Site Name	Site Code	Year / Season
3	Port Louis	PL	2019
Ward number W6	Block number 35	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Good		Photoplan 3d
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood West Chinatown	Address David Street		Construction Materials
Openings Notes		Stone Agamasse	
Roof Material Agamasse	Roof Type Flat roof	Roof Notes	Roof not visible
Siding Material Stone	Siding Notes		Covered with recent white paint
Dating Elements No	Proposed chronology		French, late french
Photo, Sketch or Audio Comment			Description



Photo 251-342

Small stone building, 1 floor, with a central door and two windows (now blocked with a wall) original windows had 2 shutters each one.

The construction technique shows use of small roughly squared stones, and large squared stones to frame windows and the door. Door and windows have an architrave on the top. Squared stones used to framing are hammered and smoothed on the sides, with a height of 30 cm.

The same squared stones have been used also for the corners of the building.

The roof level is reached by a stone ramp

Building	Site Name	Site Code	Year / Season
4	Port Louis	PL	2019
Ward number W6	Block number 35	Elevation	Measure, Length
Building/Structure Type Public Building	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Very Good		Photoplan 3d
Distinction Parameters Morphology / Shape	Bdg.Type Type G+1+A		
Neighbourhood West Chinatown	Address David Street, 18		Construction Materials
Openings Notes		Stone Wood	
Roof Material Wood	Roof Type Hip roof	Roof Notes With 2 dormer, squared wooden shingle	
Siding Material Stone	Siding Notes Regular		
Dating Elements	Inscription	Proposed chronology To be checked	
Photo, Sketch or Audio Comment			Description



Photo 343-555

Large building with annexes and perimeter wall, with a monumental entrance to the court/garden.

The main building has a facade on large squared stones, an arc-framed door, 2 windows at the 1st floor, and 2 aeration windows at the ground floor. The attic is wooden covered with 2 dormer. Original wooden shutters.

The main entrance (monumental one) is re-entrant and has a large rectangular door with 2 shutters. On the top of the door there is a framed rectangular big stones as an epigraphic space. There were some Chinese idiom...

Building	Site Name	Site Code	Year / Season
5	Port Louis	PL	2019
Ward number W6	Block number 17	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Additions/Arch.	Types of analysis	
Visibility Good	Preservation Status Adequate		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Farquhar Street	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description

Building to do: Dated plaque: 1849 / 1949

Building	Site Name	Site Code	Year / Season
6	Port Louis	<i>PL</i>	2019
Ward number W6	Block number 21	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Visibility	Preservation Status		
Distinction Parameters	Bdg.Type		
Neighbourhood	Address Farquhar St.	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description
Edificio 2 piani diroccato Farquhar st			



Building	Site Name	Site Code	Year / Season
7	Port Louis	PL	2019
Ward number W6	Block number 21	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Visibility	Preservation Status		
Distinction Parameters	Bdg.Type		
Neighbourhood	Address Farquhar St.; Corderie St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description Stores angolo Farquhar st e corderie St



Building	Site Name	Site Code	Year / Season
8	Port Louis	<i>PL</i>	2019
Ward number W6	Block number 21	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Visibility	Preservation Status		
Distinction Parameters	Bdg.Type		
Neighbourhood	Address Corderie St.	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description
Stores su corderie St vicino a 7			



Building	Site Name	Site Code	Year / Season
9	Port Louis	PL	2019
Ward number W6	Block number 26	Elevation	Measure, Length
Building/Structure Type House	Building status Original	Types of analysis Photo	
Visibility Very Good	Preservation Status Good	Photoplan 3d	
Distinction Parameters Building technique	Bdg.Type Type G+1+A	Drone	
Neighbourhood West Chinatown	Address 15, David street	Construction Materials	
Openings Notes	Wood Stone Metal		
Roof Material Wood	Roof Type Hip roof	Roof Notes Top decoration with metal pinnacle	
Siding Material Wood	Siding Notes Regular wooden planks, there is a collapse toward north		
Dating Elements Post 1860' fire?	Proposed chronology Original late 18th, probably refitted		

Photo, Sketch or Audio Comment

Description



Wooden house. Type G+1+a, it stand over a stone base made by roughly squared stones. At the ground floor as a door and 2 window, with original shaped shutters. Wooden siding, made by 16 horizontal wooden planks. First floor has 13 rows of wooden planks, 3 windows and 1 door. It has a small central terrace/balcony, today with a metal railing. There is a metal original canopy sustained by metal supports connected to the facade. The canopy is decorated with a simple carved motif. Over the 1st. Floor windows there are small canopies decorated with a simple pattern with also a central hole for ventilation.

Building	Site Name	Site Code	Year / Season
10	Port Louis	PL	2019
Ward number W6	Block number 35	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Disturbed/Restored		Types of analysis Photo
Visibility Medium	Preservation Status Inadequate		Photoplan 3d
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood West Chinatown	Address On the corner of David St. and		Construction Materials
Openings Notes The remaining openings are now shut with concrete bricks		Stone	
Roof Material	Roof Type	Roof Notes	Non present, the original probably wooden
Siding Material Stone	Siding Notes		Not refined. Restoration on joints and beds
Dating Elements		Proposed chronology	
Photo, Sketch or Audio Comment			Description



Stone building, 1 floor, with 3 doors on Renganaden Seeneevassen St. and 2 remaining doors in David St. stonework with large mostly flattened and roughly hammered basalt stones. There is a light polished frame on the stones. The bedding and joints are irregulars. Doors are not framed, and they have a carved architrave with the indent for the doors' shutters. It is musing of the roof, abandoned and the doors and missing part have been filled with moderne concrete blocks. There still the metal works for connecting the roof (probably wooden) with the side walls.

Building	Site Name	Site Code	Year / Season
11	Port Louis	PL	2019
Ward number W6	Block number 45	Elevation	Measure, Length
Building/Structure Type House	Building status Original	Types of analysis Photo	
Visibility Very Good	Preservation Status Adequate	Photoplan 3d	
Distinction Parameters Building Materials	Bdg.Type Type G		
Neighbourhood West Chinatown	Address On the corner of David St. and	Construction Materials	
Openings Notes Wooden shutters, double		Bricks Stone Metal	
Roof Material Agamasse	Roof Type Flat roof	Roof Notes The annex has a shed roof	
Siding Material Bricks	Siding Notes The annex has a stone siding		
Dating Elements	Proposed chronology French, with British additions		
Photo, Sketch or Audio Comment			Description



House (?) 1 floor building. It has 2 doors and 2 windows on Renganaden Seeneevassen St. and .1 door and 1 window on David street the floor is flat and probably realized in agamass. There is a cornice on the main building defining the height of the roof, made with brick and plaster mounded in a trapezoidal shape. The siding are plastered (original plaster) coral lime one. The main building is built with reused bricks as Bricked Faced wall (a Sacco). The corners has few reused basalt stones. There is a small canopy with metal supports anchored on the facade and corrugate roof.

The building has a second part on third

Building	Site Name	Site Code	Year / Season
12	Port Louis	PL	2019
Ward number W6	Block number 45	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		Photoplan 3d
Distinction Parameters Building technique	Bdg.Type Type G+A		
Neighbourhood West Chinatown	Address Renganaden Seeneevassen St.		Construction Materials
Openings Notes Quite simple, no decorations, no original canopy		Wood Metal	
Roof Material Wood	Roof Type Hip roof	Roof Notes With 2 metal pinnacles on the roof	
Siding Material Wood	Siding Notes Some of the planks are made by more than 1 piece		
Dating Elements	Proposed chronology	To verify	
Photo, Sketch or Audio Comment			Description



Very damaged wooden house. It stands on base of basalt blocks. On ground floor it has 1 door and 2 windows remaking, plus a wooden door open to unroofed alley. A modern very simple corrugated canopy. Windows are framed with simple rectangular wooden planks. The siding has irregular wooden horizontal planks, some of them are cut in more than 1 piece. The original door was trapezoidal framed. Roof is wooden with wooden shingles. There were 2 metal pinnacles over the roof. The state of the house is very bad, and only the eastern portion is still habited/squattered. Few pieces of corrugated metal have been used to

Building	Site Name	Site Code	Year / Season
13	Port Louis	PL	2019
Ward number W6	Block number 45	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Store	Original	Photo	
Visibility	Preservation Status	Photoplan	
Very Good	Good	3d	
Distinction Parameters	Bdg.Type	Drone	
Building technique	Type G+A		
Neighbourhood	Address		
Chinatown	Corner on Royal road and Barbeau St.	Construction Materials	
Openings Notes		Wood	
		Stone	
		Metal	
Roof Material	Wood	Roof Type	Dormer roof
		Roof Notes	Well preserved
Siding Material	Wood	Siding Notes	Repainted in light blue/gray
Dating Elements	Roof? Dormer	Proposed chronology	

Photo, Sketch or Audio Comment

Description



Store, maybe used also as house, it has a Sign" Kiaw Won 91. Store. General retailer and Motorcycle spare parts". Ground floor and attic with two dormer. On the main facade it has 3 doors and 1 window, on the north side on Barbeau St. it has 1 door and 2 window, plus a window on the attic space. It stands over a basalt base, siding are with wooden planks, regular size and horizontal. Openings are simple framed. Metal shutters. It is painted on gray with red doors and windows. The bottom plank is also red. There is a simple corrugated canopy with supports holding on the facade. Roof and dormers are wooden with wooden

Building	Site Name	Site Code	Year / Season
14	Port Louis	PL	2019
Ward number W6	Block number 45	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Very Good		
Distinction Parameters Building technique	Bdg.Type Type G+1+A		
Neighbourhood Chinatown	Address Royal Street		Construction Materials
Openings Notes	Difference in dimension and shape between ground floor and first floor	Wood Metal	
Roof Material Wood	Roof Type Dormer roof	Roof Notes	Hip roof with a dormer on each side - metal pinnacles on the
Siding Material Wood	Siding Notes		Orizzontal elements partially superimposed
Dating Elements		Proposed chronology	
Photo, Sketch or Audio Comment			Description



Photos 466-469

Store(gf?)-house with ground floor, first floor and attic with a wooden structure and metal openings. The wooden roof has one dormer for each side of the building. The facade has 2 window And a door. The shape of the lower windows is wider and longer than the upper windows.

The facade is painted in light blue and the preservation status is remarkably good. On the side of the building the sidings are not yet repainted. The building is located in Royal St., Chinatown.

Building	Site Name	Site Code	Year / Season
15	Port Louis	PL	2019
Ward number W6	Block number 35	Elevation	Measure, Lenght
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood Chinatown	Address Royal Street		Construction Materials
Openings Notes partly restored with new shutters		Stone Agamasse	
Roof Material Agamasse	Roof Type Flat roof	Roof Notes flat roof with geometric simple frame	
Siding Material Stone	Siding Notes side walls with smaller and irregular stone fragments		
Dating Elements	Building technique	Proposed chronology	
Photo, Sketch or Audio Comment			Description



Nb visibile on 3 sides, photo 464
 Large store building with flat roof in the corner between Royal St. and Sun Yat Sen St.. The store is made with stone carved blocks and agamasse roof with metal shutters. The building presents the original shutters in part of the store while the openings configuration in Royal St. has been partially adapted to obtain 4 new doors with metal shutters. On the better preserved side in Sun Yat Sen St. there are. The walls are covered with light yellow and white poorly preserved plaster. On the side of the Sun Yat Sen St. are also visible part of the original stone side wall made with smaller and

Building	Site Name	Site Code	Year / Season
16	Port Louis	PL	2019
Ward number W6	Block number 26	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Disturbed/Restored		Types of analysis Photo
Visibility Medium	Preservation Status Inadequate		
Distinction Parameters Building Materials	Bdg.Type		
Neighbourhood	Address Durd Guay St.		Construction Materials
Openings Notes		Stone Concrete	
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Ph code, DSC0465
 Part of a preexisting building absorbed in a new construction. Only a part of the original stone wall is still preserved.

Building	Site Name	Site Code	Year / Season
17	Port Louis	PL	2019
Ward number W6	Block number 48	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Color	Bdg.Type Type G+A		
Neighbourhood Chinatown	Address Royal St		Construction Materials
Openings Notes shutters restored with original design. the windows were originally doors		Wood Stone Corrugate Iron	
Roof Material Wood	Roof Type Dormer roof	Roof Notes hip roof with dormer, corrugated iron canopy	
Siding Material Wood	Siding Notes stone or wood depending on wich part of the building		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 470,71

Wooden and stone composite residential building in Royal St at the intersection with Rue Barbeau, with ground floor and attic. The complex is composed by two different part, a wooden one in Royal St. and a stone one in Rue Barbeau. The originally stone building (store/warehouse?) was soon readapted to residential use with the modification of openings and a new type of roof. To stone building was also added a wooden part on Royal St. most likely for commercial use. The side on the street has only doors on the ground floor and instead the residential side has also windows above

Building	Site Name	Site Code	Year / Season
18	Port Louis	PL	2019
Ward number W6	Block number 48	Elevation	Measure, Lenght
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type Type G+A		
Neighbourhood Chinatown	Address Rue Barbeau, 8		Construction Materials Wood
Openings Notes			
Roof Material Wood	Roof Type Hip roof	Roof Notes with dormers; metal pinnacle	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 472-76

Wooden colonial house painted in white with ground floor and attic(?). The identification of the architectural feature is difficult due to the very poor visibility: a great tree in the garden is covering part of the roof and higher walls of the house and also the property is enclosed in high walls made of carved stone blocks. Nevertheless, the house presents some monumental characteristics and a very fine and decorated enclosed front element with columns and decorated frame. On the attic, a balcony with two doors is surrounded by a hip roof with dormers. The house has also a considerable

Building	Site Name	Site Code	Year / Season
19	Port Louis	PL	2019
Ward number W6	Block number 48	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood Chinatown	Address Rue Barbreau		Construction Materials
Openings Notes		Stone Metal	
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 477
Remains of stone building (store/warehouse type) adapted with corrugated metal to form a smaller space. Of the original building remains only the lower part of the facade and a part of the side wall, also in stone.

Building	Site Name	Site Code	Year / Season
20	Port Louis	PL	2019
Ward number W6	Block number 48	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood Chinatown	Address La Paix St, 33		Construction Materials
Openings Notes		Wood Metal	
Roof Material Wood	Roof Type	Roof Notes	metal pinnacles; rectangular shingles
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 478

Wooden house, probably restored with metal elements, with very poor visibility. Throuout the vegetation and the high fenceare visible only a few traits as the vooden hip foor, some metal frames with decorations and a decorated vertical element.

Building	Site Name	Site Code	Year / Season
21	Port Louis	PL	2019
Ward number W6	Block number 48	Elevation	Measure, Length
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Color	Bdg.Type Type G+A		
Neighbourhood Chinatown	Address Royal st		Construction Materials
Openings Notes the door on the left is smaller, possible adaptation of a window		Stone Metal	
Roof Material Corrugate	Roof Type Gable roof	Roof Notes restored	
Siding Material Stone	Siding Notes a window in the attic on the side		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 479

Store/Warehouse in stone with 4 openings on the main facade, recently painted in yellow, white and red. The gable roof with a short canopy, in corrugated iron was probably wooden in the original design. Thank to his position on one of the main street of the neighbourhood, the building has maintained his commercial use. A commemorative plaque indicates "N. V. 1923", might determine the date of construction or the latest substantial restoration.

Building	Site Name	Site Code	Year / Season
22	Port Louis	PL	2019
Ward number W6	Block number 49	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Replaced/Modern		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Building Materials	Bdg.Type		
Neighbourhood Chinatown	Address Rue Barbeau		Construction Materials
Openings Notes		Stone	
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 480

This building is visible only for a small portion due to the recent/modern superfections and variations. Of a precedent building in well carved and refined squared stones remains only a small portion of the ground floor. The wall is made of medium stones with abundant white mortar, probably recently restored. On the right side still visible of the wall, there are bigger stones in the texture, disposed as a frame for a preexisting opening subsequently enlarged to reach the actual dimensions. Aside for these small portions of walls, very little is visible of the original configuration. Hence, it is impossible to

Building	Site Name	Site Code	Year / Season
23	Port Louis	PL	2019
Ward number W6	Block number 49	Elevation	Measure, Length
Building/Structure Type Store	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type Type G+A		
Neighbourhood Chinatown	Address Sir Seegosagur Ramgoolam St.		Construction Materials
Openings Notes number and disposition of openings difficult to determine due to the presence of commercial activities on the front		Stone Corrugate Iron Concrete	
Roof Material Corrugate	Roof Type Dormer roof	Roof Notes original roof maybe wooden	
Siding Material Stone	Siding Notes stones with irregular shape, visible on the side		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 481-483

Store/Warehouse made originally in stone with restored corrugate iron roof. Covered on the front by the metal structure of the market, with short metal canopy, difficult visibility.

The building has been elevated and readapted with concrete additions. The roof was originally probably made of wooden elements and a little dormered window has been maintained also in the new configuration. On the side of the building the original stone wall is preserved, with irregular shaped small to medium stone elements. The facade is now difficult to read due to the presence of a thin stone dark spots

Building	Site Name	Site Code	Year / Season
24	Port Louis	PL	2019
Ward number W6	Block number 49	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Disturbed/Restored		Types of analysis Photo
Visibility Very Good	Preservation Status Good		
Distinction Parameters Morphology / Shape	Bdg.Type Type G+1+A		
Neighbourhood Chinatown	Address La Paix St. 47		Construction Materials
Openings Notes shutters seem all new/restored		Concrete Corrugate Iron Wood	
Roof Material Corrugate	Roof Type Dormer roof	Roof Notes wide dormer with a central window and lateral glass and	
Siding Material	Siding Notes not visible		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 484-85

Store/warehouse sufficiently well preserved with ground floor, first floor and attic. Construction material of the ground floor is difficult to inspect due to the presence of a thick plaster. The first floor seems made of concrete based materials but is articulated in shape and morphology like other stone observed building. It is possible that the present configuration of the building is due to a restoration that preserved the original morphology. On this floor, many doors and windows with glass and wood shutters open on a balcony with decorated railings. At the highest level, the attic stands under a

Building	Site Name	Site Code	Year / Season
25	Port Louis	PL	2019
Ward number W6	Block number 49	Elevation	Measure, Length
Building/Structure Type Store	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Morphology / Shape	Bdg.Type Type G		
Neighbourhood Chinatown	Address Remi Olier St, 64		Construction Materials
Openings Notes on the secondary side openings with a small step in front		Stone Concrete Wood	
Roof Material Concrete	Roof Type Flat roof	Roof Notes on restoration/reshaping when surveyed	
Siding Material Stone	Siding Notes regular squared blocks, thick painting		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 486-487

Store building in sone with GF and many openings on the main sides, the openings on La Paix St. have a small step right in front of them. The building has been modified in the upper part. The regular stone texture is visible only in some sparse spots, covered by the white, blue and yellow thick painting. All the shutters are new, apart maybe for the red one and the blue one in Remi Olier St.

Building	Site Name	Site Code	Year / Season
26	Port Louis	PL	2019
Ward number W6	Block number 49	Elevation	Measure, Length
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Color	Bdg.Type Type G		
Neighbourhood Chinatown	Address Remi Olier st, 66		Construction Materials
Openings Notes the original openings appears to have stone frames with alternate long-short sequence of stones and an architrave made with a long element with above a shorter central		Stone Agamasse Wood	
Roof Material Agamasse	Roof Type Flat roof	Roof Notes flat agamasse roof with linear vertical shape on the front	
Siding Material Stone	Siding Notes rectangular stones, very regular		
Dating Elements type of roof	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 488-89

Store with only GF with stone walls made with rectangular and very regular elements. The roof, in agamasse, with straight design. The building has been readapted/restored with the addition of a small canopy in corrugate iron and also the wide opening on the right is likely to be opened recently. The store is partially covered with blue and yellow painting but the laying is visible underneath. Three of the four openings on the main facade seems to be the original ones.

Building	Site Name	Site Code	Year / Season
27	Port Louis	PL	2019
Ward number W6	Block number 50	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood Chinatown	Address Remi Ollier St, 56		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Ruins of a large house with a metal decorated fine gate and a concrete and stone elegant fence. The architectural details of the house are uncertain because of the ruinous state of the building. KEEP IT?

Building	Site Name	Site Code	Year / Season
28	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type Type G+A		
Neighbourhood Chinatown	Address Remi Ollier st		Construction Materials
Openings Notes	the right window on Remi Ollier St. is wooden; the other metal shutters seem new	Wood Stone Corrugate Iron	
Roof Material Corrugate	Roof Type Dormer roof	Roof Notes	a little dormer is visible on the side on the building in Sun Yat
Siding Material Wood	Siding Notes		some planks are crumbled
Dating Elements		Proposed chronology	
Photo, Sketch or Audio Comment			Description



Photo 493

Wooden shop in Remi Ollier St..The building, on the GF only, has a completely wooden structure built upon a stone base visible at the ground level. The rest of walls, painted in gray, are made of wood plank, horizontally disposed. The roof, recently restored is incorrugate iron and include a short canopy on the street sides. The shutters are in metal and wood, the metal ones seem new. On Sun Yat Sen St. side of the building an annex with flat roof is made with corrugated iron incorporating a stone wall portion still visible going further (building n. 29)

Building	Site Name	Site Code	Year / Season
29	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Original	Types of analysis Photo	
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood Chinatown	Address Sun Yat Sen St.	Construction Materials	
Openings Notes only a little portion of an original stone frame is still visible on the wall		Stone Corrugate Iron	
Roof Material Corrugate	Roof Type Flat roof	Roof Notes restored roof	
Siding Material Stone	Siding Notes part of the siding is now refitted with iron sheets		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 495

Wall of a preexisting building partially enclosed now in a new construction (building 28). This portion of the original wall is preserved up to the roof and is made of roughly squared basaltic stones with an almost regular setting joined with abundant white lime mortar, probably refilled. On the right side, are visible some bigger blocks part of a frame for an opening, probably a door. The wall is now effectively part of the building n. 28, with corrugate iron flat roof. The wall presents sparse traces of yellow paint.

Building	Site Name	Site Code	Year / Season
30	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type Store	Building status Additions/Arch.		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood Chinatown	Address Sun Yat Sen St		Construction Materials Stone
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 497

Stone portion of a preexisting building enclosed in a modern store with structural addition in concrete and corrugate iron roof. Poor visibility of the remaining portion of the wall. The structure is partially covered with yellow painting.

Building	Site Name	Site Code	Year / Season
31	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type Store	Building status Disturbed/Restored		Types of analysis Photo
Visibility Medium	Preservation Status Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood	Address Sun Yat sen st		Construction Materials Stone
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 498
Modern store on Sun Yat Sen St. with restore portion of original stone walls inside, heavily restored with new painted plaster and refilled beds and joints. The original use of the building, is difficult to determine.

Building	Site Name	Site Code	Year / Season
32	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Morphology / Shape	Bdg.Type Type G		
Neighbourhood Chinatown	Address Sun Yat Sen St.		Construction Materials
Openings Notes original shutter but recently repainted in vivid red		Stone Corrugate Iron Wood Concrete	
Roof Material Corrugate	Roof Type Flat roof	Roof Notes flat roof eith small canopy on the front	
Siding Material Concrete	Siding Notes stone and concrete		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 503-505

Remaining part of a stone store overlooking the street, with only one wooden door left. The building, with corrugate iron flat roof and a small canopy on the front, was recently repainted and decorated witha colourfull murales. The building han been reshaped with concrete adjuncts on the side. In front of the only opening left, there is a small step on the ground.

Building	Site Name	Site Code	Year / Season
33	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Store	Additions/Arch.	Photo	
Visibility	Preservation Status		
Good	Very Good		
Distinction Parameters	Bdg.Type		
Color	Type G		
Neighbourhood	Address		
Chinatown	Sun Yat Sen Street	Construction Materials	
Openings Notes	3 metal, original but repainted; 1 larger wood restored	Stone	
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 506-9
Preexistent stone store incorporated in a new building. Colourfull murales on front. Three of the original shutters are preserved and also the stone front wall.

Building	Site Name	Site Code	Year / Season
34	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type Type G+A		
Neighbourhood Chinatown	Address Sun Yat Sen St., 23		Construction Materials
Openings Notes barely visible		Wood Metal	
Roof Material Wood	Roof Type Dormer roof	Roof Notes dormer on the front	berely visible
Siding Material Wood	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 510-11

Large wooden house with GF, attic and a garden. The flourishing vegetation and the high stone fence with metal gates prevent the full visibility of the architectural features. The house seems entirely in wood, with roof covered in rectangular small shingle, a part for some metal sheet on the edges of the roof and the traditional metal pinnacles. Although the house is still perfectly standing, the preservation status seems precarious, and some collapses and broken planks are visible on the front.

Building	Site Name	Site Code	Year / Season
35	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Good		Photoplan Drone
Distinction Parameters Building technique	Bdg.Type Type G+1		
Neighbourhood Chinatown	Address Royal st		Construction Materials
Openings Notes Some of them, if not all of them are restored		Wood Metal Corrugate Iron	
Roof Material Wood	Roof Type M Shaped	Roof Notes	Two parts one wood and one corrugated iron maybe restored
Siding Material Wood	Siding Notes Irregularly posed on the side		
Dating Elements	Roof tiles, dormers, building technique Location on royal st	Proposed chronology	
Photo, Sketch or Audio Comment			Description



Photo 512-515

Store/office in wooden sidings, stone base and mixed shutters, original (metal) and new ones. The roof is in wood rectangular shingle with two dormer on the front and just one on the other side; also metal pinnacles on the edges. The building has a metal balcony with wooden floor, with decorated railings. The stone base is composed by one course of heavy big blocks barely visible because of the covering red plaster. The store has been recently repainted in vivid red color on the ground floor, instead the first one is not painted. Doors and windows are painted in shades of red light blue in the first

Building	Site Name	Site Code	Year / Season
36	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type House	Building status Disturbed/Restored		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type Type G+A		
Neighbourhood Chinatown	Address Remy Ollier St., inner side of the block		Construction Materials
Openings Notes woodes shutters		Wood Metal Concrete Corrugate Iron	
Roof Material Wood	Roof Type Hip roof	Roof Notes metal pinnacles; rectangular wooden shingle in horizontal	
Siding Material Wood	Siding Notes sidin type not visible		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Inner block photo 516-18

Wooden house reshaped and enclosed in a new building with metal and concrete additions. The original part is now in a precarious state of conservation and is visible in the inner part of the block, when the front of the building is completely modern/reshaped. Part of the original attic is visible, made in wooden planks and shingle roof with a decorated triangular section on the edge of the roof instead of a dormer. This appendix is decorated with geometric motifs a wooden frame with ovals. The edges of the roof are decorated with metal pinnacles. On the side, one can see the original wooden shutters.

Building	Site Name	Site Code	Year / Season
37	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type House	Building status Additions/Arch.		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood Chinatown	Address Remy Ollier St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Foundation levels Photo 519
Remainings of a recently dismantled house with stone base and wood. TO KEEP?

Building	Site Name	Site Code	Year / Season
38	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood Chinatown	Address Remy Ollier St., inner side of the block		Construction Materials
Openings Notes barely visible		Wood Corrugate Iron	
Roof Material Wood	Roof Type Hip roof	Roof Notes metal pinnacle on top	
Siding Material Wood	Siding Notes barely visible		
Dating Elements type of roof	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Inner block photo 521

Wooden house with corrugate iron roof and metal pinnacle on top. Restore/reshaped; the roof originally was made of wooden shingle, some fo wichstill preserved on the edge. openings and windows not visible. In front of the house, a stone and metal gate prevents an open view of the building.

Building	Site Name	Site Code	Year / Season
39	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood Chinatown	Address Remy Ollier St.		Construction Materials
Openings Notes clipped wooden plank under the window		Wood Iron	
Roof Material Metal	Roof Type Hip roof	Roof Notes	
Siding Material Metal	Siding Notes the metal sheets of the main facade imitates the wooden ones		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 522

Wooden Store; overlooks the street. The structure is entirely sided by iron sheets with wooden frames for the openings. The building has 2 doors and a window on front, the central door with a small step in front. A thick layer of light grey painting covers up the main facade. The roof has two metal pinnacles on the edge and the openings are underlined with white simple wooden frames.

Building	Site Name	Site Code	Year / Season
40	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length 8
Building/Structure Type House	Building status Disturbed/Restored		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood Chinatown	Address Remy Ollier St.		Construction Materials
Openings Notes		Metal	
Roof Material Metal	Roof Type Hip roof	Roof Notes	metal pinnacles on top
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 524

Only the roof in metal plates of this building is visible from Remy Ollier St. because it is located in the inner block and another store cover its sight.

Building	Site Name	Site Code	Year / Season
41	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length 14
Building/Structure Type To be defined	Building status Additions/Arch.		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg. Type Type G		
Neighbourhood Chinatown	Address Remy Ollier St.		Construction Materials
Openings Notes upper frame of the door is underlined with second clipped decorative element		Wood Metal Corrugate Iron Iron	
Roof Material Metal	Roof Type Hip roof	Roof Notes metal pinnacle on the edge	
Siding Material Wood	Siding Notes with restored elements		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 525

Wooden store subsequently enlarged on the back with appendix in corrugate iron. The front side on the street seems original, apart from the restored roof in metal sheets. The wooden plaks of the facade are painted in white while the original door wooden door has been recently repainted in red. A small canopy in corrugate iron extends toward the street.

Building	Site Name	Site Code	Year / Season
42	Port Louis	PL	2019
Ward number W6	Block number 44	Elevation	Measure, Length 5
Building/Structure Type	Building status	Types of analysis	
Store	Disturbed/Restored	Photo	
Visibility	Preservation Status		
Good	Good		
Distinction Parameters	Bdg.Type		
Color	Type G+A		
Neighbourhood	Address		
Chinatown	Remy Ollier St.	Construction Materials	
Openings Notes		Stone	
		Metal	
Roof Material	Corrugate	Roof Type	Roof Notes
		Flat roof	
Siding Material		Siding Notes	
Dating Elements		Proposed chronology	
Photo, Sketch or Audio Comment			Description



Front side photo 523
 Stone store with GF and corrugate iron roof, probably restored. The thick yellow plaster on the front of the building covers the stone blocks. On the front, with one large opening, a small canopy overlooks the sidewalk.

Building	Site Name	Site Code	Year / Season
43	Port Louis	PL	2019
Ward number W6	Block number 54	Elevation	Measure, Length 10
Building/Structure Type To be defined	Building status Additions/Arch.		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Color	Bdg. Type Type G		
Neighbourhood Chinatown	Address Sun Yat Sen St.		Construction Materials
Openings Notes		Stone Metal Concrete	
Roof Material Metal	Roof Type Gable roof	Roof Notes roof restored/reshaped	
Siding Material Stone	Siding Notes coursed masonry		
Dating Elements masonry	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 526,
Stone warehouse building with modern superfection/restoration. The remaining side visible - the one on Sun Yat Sen St. - has only one original door left, with metal shutters and a short canopy above, possibly added after to the original construction. The stone texture is visible up until approximately 1.5m from the ground level. Below, a thick yellow/cream plaster covers the wall. The stones are regularly disposed in horizontal courses and the door has a well distinguishable stone frame with bigger blocks. The same wall continues also on the left (see also without information throughout the

Building	Site Name	Site Code	Year / Season
44	Port Louis	PL	2019
Ward number W6	Block number 54	Elevation	Measure, Length 25
Building/Structure Type Store/Office	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Good		
Distinction Parameters Building technique	Bdg. Type Type G+1		
Neighbourhood Chinatown	Address Sir Seewoosagur Ramgoolam St.		Construction Materials
Openings Notes decorated stone frames around doors and windows; peculiar shape of doors and windows of the gf with upper decorated element - wavy		Stone Wood Corrugate Iron Metal	
Roof Material Corrugate	Roof Type Gambrel roof	Roof Notes	
Siding Material Stone	Siding Notes gf stone 1f wood		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 527-29

Store/office building with GF+1 floors. Stone ground floor in coursed masonry with big regularly carved blocks. 8 openings with decorated frames and metal shutters (wavy upper element in door and windows) and also geometric decorations on stone blocks above the openings. Wooden first floor with sidings in wooden planks. 12 openings, alternate window-door sequence (6d + 6w). Wooden shutters with simple squared frames. Corrugate iron simple roof with tight canopy sustained with wooden vertical elements, covering a balcony with decorated railing with elaborate motifs.

Building	Site Name	Site Code	Year / Season
45	Port Louis	PL	2019
Ward number W6	Block number 54	Elevation	Measure, Length 16
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Good		
Distinction Parameters Building Materials	Bdg.Type Type G		
Neighbourhood Chinatown	Address Sir Seewoosagur Ramgoolam St.		Construction Materials
Openings Notes		Concrete Metal	
Roof Material Concrete	Roof Type Flat roof	Roof Notes	
Siding Material Concrete	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 531
Store, only Ground floor. Concrete building with 1 opening and two shop windows. Flat concrete roof with upper decorative plaque indicating the date of construction "C; 1939; J". Short concrete canopy on the front.

Building	Site Name	Site Code	Year / Season
46	Port Louis	PL	2019
Ward number W6	Block number 54	Elevation	Measure, Length 11
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Very Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood Chinatown	Address Sir Seewoosagur Ramgoolam St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 530
First and second floors covered by wooden tiles

Building	Site Name	Site Code	Year / Season
47	Port Louis	PL	2019
Ward number W6	Block number 43	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood Chinatown	Address Rue Emmanuel anquetil		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 532

Building	Site Name	Site Code	Year / Season
48	Port Louis	PL	2019
Ward number W6	Block number 43	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood Chinatown	Address Rue Emmanuel anquetil		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 533

Building	Site Name	Site Code	Year / Season
49	Port Louis	PL	2019
Ward number W6	Block number 43	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood Chinatown	Address Royal st		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description

Ph 534-36



Building	Site Name	Site Code	Year / Season
50	Port Louis	PL	2019
Ward number W6	Block number 34	Elevation	Measure, Length
Building/Structure Type To be defined	Building status		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Color	Bdg.Type		
Neighbourhood	Address Royal road		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 537

Building	Site Name	Site Code	Year / Season
51	Port Louis	PL	2019
Ward number W6	Block number 34	Elevation	Measure, Length
Building/Structure Type Store	Building status		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood Chinatown	Address Queen st		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo

Building	Site Name	Site Code	Year / Season
52	Port Louis	PL	2019
Ward number W6	Block number 34	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
House	Disturbed/Restored	Photo	
Visibility	Preservation Status		
Good	Good		
Distinction Parameters	Bdg.Type		
Color			
Neighbourhood	Address		
Chinatown	Venting st	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 539

Building	Site Name	Site Code	Year / Season
53	Port Louis	PL	2019
Ward number W6	Block number 25	Elevation	Measure, Length
Building/Structure Type Warehouse	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood	Address Farquhar Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Doubled building photo 540

Building	Site Name	Site Code	Year / Season
54	Port Louis	PL	2019
Ward number W6	Block number 25	Elevation	Measure, Length
Building/Structure Type	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Farquhar Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 541

Building	Site Name	Site Code	Year / Season
55	Port Louis	PL	2019
Ward number W6	Block number 25	Elevation	Measure, Length
Building/Structure Type Warehouse	Building status		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Farquhar Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Ph 552

Building	Site Name	Site Code	Year / Season
56	Port Louis	PL	2019
Ward number W6	Block number 24	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dr. Joseph Rivière st		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 543

Building	Site Name	Site Code	Year / Season
57	Port Louis	PL	2019
Ward number W4	Block number 203	Elevation	Measure, Length
Building/Structure Type House	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir Virgil Naz St		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 800

Building	Site Name	Site Code	Year / Season
58	Port Louis	PL	2019
Ward number W4	Block number 204	Elevation	Measure, Length
Building/Structure Type House	Building status		Types of analysis Photo
Visibility Medium	Preservation Status Very Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood	Address Sir Virgil Naz Street, inner block		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 801-02

Building	Site Name	Site Code	Year / Season
59	Port Louis	PL	2019
Ward number W4	Block number 204	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Store	Disturbed/Restored	Photo	
Visibility	Preservation Status	Photoplan	
Very Good	Very Good		
Distinction Parameters	Bdg.Type		
Building technique	Type G+A		
Neighbourhood	Address	Construction Materials	
	Sir Virgil Naz St. 54		
Openings Notes	Originals ?? Frame under the door particularly cut	Wood Stone Corrugate Iron	
Roof Material	Corrugate	Roof Type Dormer roof	Roof Notes Two overlapped iron plates
Siding Material	Wood	Siding Notes Some cuttings and element restoration	
Dating Elements		Proposed chronology	
Photo, Sketch or Audio Comment			Description



Photo 803-10

Store type building with wooden sidings, stone base and iron corrugated roof. Ground floor and attic. The wooden elements of the siding are well disposed although some cut and conjunction are visible. The ground floor is divided in two different color, maybe dividing two properties, but the building was built altogether and has the same characteristics (??). One part in painted in lighter blue. The openings have a simple frame painted in white. The roof, in corrugated iron is gable type with a dormer on the frontal side. On the lateral side of the building the window in the first floor has a

Building	Site Name	Site Code	Year / Season
60	Port Louis	PL	2019
Ward number W4	Block number 204	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address La Paix St		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 36-37

Building	Site Name	Site Code	Year / Season
61	Port Louis	PL	2019
Ward number W4	Block number 204	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address La Paix St		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 38-40
Gf stone covered in plaster, 1 floor wood, roof overlapped iron plates, balcony concrete

Building	Site Name	Site Code	Year / Season
62	Port Louis	PL	2019
Ward number W4	Block number 204	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Very Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir Virgil Naz St		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 41-44
 Date on the front 1865
 Composite building
 Interesting technique and decorative parts

Building	Site Name	Site Code	Year / Season
63	Port Louis	PL	2019
Ward number W4	Block number 206	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Good		Photoplan Drone
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood Maalabars	Address Etienne Pellereau Street		Construction Materials
Openings Notes		Stone Wood Corrugate Iron Concrete	
Roof Material Corrugate	Roof Type Flat roof	Roof Notes Plain in corrugated iron	
Siding Material Stone	Siding Notes Part of the annex siding is wooden		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 46-49
small building on the street with annexes (house??). Stone, concrete white plaster. Iron corrugated roof overlapped.
Angular stone bigger than other, chaotically posed and smaller ones for the facade. A part for the main building, the annexes are partially wooden. The wooden annex could be the external bathroom. The structure continues until the river level, below the street level.
Main facade painted in white plaster, annexes in concrete white plaster.
On the back, multiple restoration and modifications. Side windows were probably

Building	Site Name	Site Code	Year / Season
64	Port Louis	PL	2019
Ward number W4	Block number 206	Elevation	Measure, Length
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Etienne Pellereau Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 184

Building	Site Name	Site Code	Year / Season
65	Port Louis	PL	2019
Ward number W4	Block number 202	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir Virgil Naz Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 185

Building	Site Name	Site Code	Year / Season
66	Port Louis	PL	2019
Ward number W4	Block number 209	Elevation	Measure, Length
Building/Structure Type Store/Office	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Sir Virgil Naz St		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 186

Building	Site Name	Site Code	Year / Season
67	Port Louis	PL	2019
Ward number W4	Block number 209	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Store	Additions/Arch.	Photo	
Visibility	Preservation Status		
Good	Adequate		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Sir Virgil Naz St	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment		Description	



Photo 187
This building and the subsequent are part of a same design and technique but separated by a roofed alley

Building	Site Name	Site Code	Year / Season
68	Port Louis	PL	2019
Ward number W4	Block number 209	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood	Address Sir Virgil Naz St		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 188

Building	Site Name	Site Code	Year / Season
69	Port Louis	PL	2019
Ward number W4	Block number 208	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue Dauphine		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 189
Oriented differently, north-east side

Building	Site Name	Site Code	Year / Season
70	Port Louis	PL	2019
Ward number W4	Block number 208	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dauphine Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 192
Ancient house on the back side of a modern concrete one. In ruins

Building	Site Name	Site Code	Year / Season
71	Port Louis	PL	2019
Ward number W4	Block number 208	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir Virgil Naz St		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 194-96
Remarkable shape and technique but many tree inside and upfront

Building	Site Name	Site Code	Year / Season
72	Port Louis	PL	2019
Ward number W4	Block number 210	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Rue Arsenal		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 197
Former house reduced and partially ruined. Today only a small portion of the original building remains preserved.

Building	Site Name	Site Code	Year / Season
73	Port Louis	PL	2019
Ward number W4	Block number 210	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
House	Disturbed/Restored	Photo	
Visibility	Preservation Status		
Good	Good		
Distinction Parameters	Bdg.Type		
Building Materials			
Neighbourhood	Address		
	Rue Arsenal	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 198
Wood sidings
Iron corrugated roof

Building	Site Name	Site Code	Year / Season
74	Port Louis	PL	2019
Ward number W4	Block number 207	Elevation	Measure, Length
Building/Structure Type House	Building status	Types of analysis Photo	
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue Arsenal 58	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 199
Remarkable housing type well preserved.
Preserved annexes

Building	Site Name	Site Code	Year / Season
75	Port Louis	PL	2019
Ward number W4	Block number 207	Elevation	Measure, Length
Building/Structure Type House	Building status	Types of analysis Photo	
Visibility Good	Preservation Status Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood	Address Rue Arsenal	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo

Building	Site Name	Site Code	Year / Season
76	Port Louis	PL	2019
Ward number W4	Block number 207	Elevation	Measure, Length
Building/Structure Type House	Building status	Types of analysis Photo	
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue Arsenal	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo

Building	Site Name	Site Code	Year / Season
77	Port Louis	PL	2019
Ward number W4	Block number 207	Elevation	Measure, Length
Building/Structure Type Store	Building status Replaced/Modern		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Rue Arsenal		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo
Probably rebuilt building with previous shape of a gable roofed store

Building	Site Name	Site Code	Year / Season
78	Port Louis	PL	2019
Ward number W4	Block number 207	Elevation	Measure, Length
Building/Structure Type House	Building status Additions/Arch.		Types of analysis Photo
Visibility Poor	Preservation Status Good		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Rue Dauphine 46		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 207-208
 Wooden house restored and modified but still visible in the inner space of the block.
 Probably Muslim inhabitants, Arabic inscriptions on the front and inside.

Building	Site Name	Site Code	Year / Season
79	Port Louis	PL	2019
Ward number W4	Block number 211	Elevation	Measure, Length
Building/Structure Type To be defined	Building status		Types of analysis Photo
Visibility Medium	Preservation Status Inadequate		
Distinction Parameters Building Materials	Bdg.Type		
Neighbourhood	Address Rue Dauphine		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 209-211
Surviving annex of a wider construction no more visible.

Building	Site Name	Site Code	Year / Season
80	Port Louis	PL	2019
Ward number W4	Block number 224	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Suffren		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 212

Building	Site Name	Site Code	Year / Season
81	Port Louis	PL	2019
Ward number W4	Block number 224	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Very Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood	Address Suffren		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 213
Still inhabited

Building	Site Name	Site Code	Year / Season
82	Port Louis	PL	2019
Ward number W4	Block number 224	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Very Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dr. Eugene Laurent St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Mansard roof with dormers.
Photo 214-216

Papabile per rilievo anche se coperta da recinto esterno

Building	Site Name	Site Code	Year / Season
83	Port Louis	PL	2019
Ward number W4	Block number 224	Elevation	Measure, Lenght
Building/Structure Type Public Building	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Very Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dr. Eugene Laurent St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Foundation dated back to 1893.
 Photo 217-219
 All the north and east part of the property is closed by a wall made by stones.

Building	Site Name	Site Code	Year / Season
84	Port Louis	PL	2019
Ward number W4	Block number 224	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dauphine Street, inner block		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 220-221

Building	Site Name	Site Code	Year / Season
85	Port Louis	PL	2019
Ward number W4	Block number 224	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dauphine Street, inner block		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements Photo, Sketch or Audio Comment	Proposed chronology		Description
		Photo 222-223	



Building	Site Name	Site Code	Year / Season
86	Port Louis	PL	2019
Ward number W4	Block number 219	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Store	Original	Photo	
Visibility	Preservation Status		
Good	Good		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Jumma Mosque Street	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description

Photo 226-229



Building	Site Name	Site Code	Year / Season
87	Port Louis	PL	2019
Ward number W4	Block number 219	Elevation	Measure, Length
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Jummah Mosque St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 229-232

Building	Site Name	Site Code	Year / Season
88	Port Louis	PL	2019
Ward number W4	Block number 219	Elevation	Measure, Length
Building/Structure Type Public Building	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Very Good		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Bourbon Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 236-237

Building	Site Name	Site Code	Year / Season
89	Port Louis	PL	2019
Ward number W4	Block number 225	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dr. Eugene Laurent St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 238-240

Building	Site Name	Site Code	Year / Season
90	Port Louis	PL	2019
Ward number W4	Block number 225	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Mgr. Gonin		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 241-243

Building	Site Name	Site Code	Year / Season
91	Port Louis	PL	2019
Ward number W3	Block number 78	Elevation	Measure, Lenght
Building/Structure Type Cathedral	Building status Disturbed/Restored		Types of analysis Photo
Visibility Very Good	Preservation Status Very Good		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Bourbon Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



One of the best architectural accomplishments of the 20th century Mauritius. Built during the governorship of Magon beetwen 1752-1756. It was rebuild a large part of the cathedral, including the foundations and it is was finally consecrated by Monseigneur Leon 13 years later.

Photo 243-248

Building	Site Name	Site Code	Year / Season
92	Port Louis	PL	2019
Ward number W3	Block number 72	Elevation	Measure, Length
Building/Structure Type Public Building	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Very Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dauphine Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description

Photo 249-250,252



Building	Site Name	Site Code	Year / Season
93	Port Louis	PL	2019
Ward number W3	Block number 72	Elevation	Measure, Length
Building/Structure Type Warehouse	Building status Original	Types of analysis	
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir Virgille Naz	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 251,253-255

Building	Site Name	Site Code	Year / Season
94	Port Louis	PL	2019
Ward number W3	Block number 72	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Store	Original	Photo	
Visibility	Preservation Status		
Good	Good		
Distinction Parameters	Bdg.Type		
Building Materials			
Neighbourhood	Address		
	Sir Virgille Naz	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 251,256-258

Building	Site Name	Site Code	Year / Season
95	Port Louis	PL	2019
Ward number W3	Block number 72	Elevation	Measure, Length
Building/Structure Type Warehouse	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir Virgille Naz		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 259-260
The building is visible on the the north waster side and is made by stones.

Building	Site Name	Site Code	Year / Season
96	Port Louis	PL	2019
Ward number W3	Block number 72	Elevation	Measure, Length
Building/Structure Type Warehouse	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		Photoplan
Distinction Parameters Building technique	Bdg.Type Type G		
Neighbourhood	Address Sir Virgille Naz		Construction Materials
Openings Notes		Stone	
Roof Material	Roof Type	Roof Notes	
Siding Material Stone	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 261-262

The stone warehouse with for the frames and smaller ones for the sidings located in the nord western half of block 72. The building was recently restored with a superfetation of a concrete building. It has three doors on the north waster wall.

The building was probably restored or

Building	Site Name	Site Code	Year / Season
97	Port Louis	PL	2019
Ward number W4	Block number 222	Elevation	Measure, Length
Building/Structure Type Warehouse	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir Virgille Naz		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo

Building	Site Name	Site Code	Year / Season
98	Port Louis	PL	2019
Ward number W4	Block number 221	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address SSR		Construction Materials
Openings Notes		Stone Wood	
Roof Material Wood	Roof Type Hip roof	Roof Notes + dormers	
Siding Material Stone	Siding Notes Wood with different technique in the front and back		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 654-652

The building é visibile sul retro accedendo da Barboun St. tramite un cancello trovato aperto. Il retro é composto interamente in legno (piano terra e primo piano) mentre la facciata principale su SSR conserva solo il primo piano in legno mentre il piano terra é oggi occupato da alcune attività commerciali e con muro intonacato, pertanto non é possibile interpretarne la tecnica costruttiva. Il primo piano è interamente un dormer roof con pareti esterne in legno rustic vee.

In the inner garden the wooden porch is in ...

Building	Site Name	Site Code	Year / Season
99	Port Louis	PL	2019
Ward number W4	Block number 70	Elevation	Measure, Length
Building/Structure Type Public Building	Building status Disturbed/Restored		Types of analysis Photo
Visibility Very Good	Preservation Status Very Good		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Place Nelson Mandela		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 657-660

The construction of the theatre started in 1820. It was inaugurated on 1822 and is one of the oldest in the Southern Hemisphere.

Building	Site Name	Site Code	Year / Season
100	Port Louis	PL	
Ward number W4	Block number 70	Elevation	Measure, Length
Building/Structure Type Public Building	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Very Good		
Distinction Parameters Morphology / Shape	Bdg.Type		
Neighbourhood	Address Place Nelson Mandela		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Lamppost made by iron in the middle of the place Nelson Mandela.

Building	Site Name	Site Code	Year / Season
101	Port Louis	PL	2019
Ward number W3	Block number 70	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Store	Original	Photo	
Visibility	Preservation Status		
Good	Good		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Sir Seewoosagur Ramgoolam	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description

Photo 664-667



Building	Site Name	Site Code	Year / Season
102	Port Louis	PL	2019
Ward number W3	Block number 68	Elevation	Measure, Lenght
Building/Structure Type	Building status Original	Types of analysis Photo	
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Bourbon St.	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 671-673

Building	Site Name	Site Code	Year / Season
103	Port Louis	PL	2019
Ward number W3	Block number 68	Elevation	Measure, Length
Building/Structure Type	Building status Original	Types of analysis Photo	
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Bourbon St.	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Building	Site Name	Site Code	Year / Season
104	Port Louis	PL	2019
Ward number W3	Block number 67	Elevation	Measure, Length
Building/Structure Type House	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Bourbon St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 680-682

Building	Site Name	Site Code	Year / Season
105	Port Louis	PL	2019
Ward number W3	Block number 67	Elevation	Measure, Length
Building/Structure Type House	Building status Replaced/Modern		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Color	Bdg.Type		
Neighbourhood	Address Bourbon St. 25		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 683,684

Building	Site Name	Site Code	Year / Season
106	Port Louis	PL	2019
Ward number W3	Block number 67	Elevation	Measure, Length
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Bourbon St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 685

Building	Site Name	Site Code	Year / Season
107	Port Louis	PL	2019
Ward number W3	Block number 67	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 687,688

Building	Site Name	Site Code	Year / Season
108	Port Louis	PL	2019
Ward number W3	Block number 67	Elevation	Measure, Length
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir Seewoosagur Ramgoolam		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 694-695

Building	Site Name	Site Code	Year / Season
109	Port Louis	PL	2019
Ward number W3	Block number 67	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir Seewoosagur Ramgoolam		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 700-703

Building	Site Name	Site Code	Year / Season
110	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
House	Original	Photo	
Visibility	Preservation Status		
Good	Good		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Rue L'Eglise	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment		Description	



Photo 705-708

Building	Site Name	Site Code	Year / Season
111	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Avenue Suffren		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 710-711

Building	Site Name	Site Code	Year / Season
112	Aapravasi Ghat	AG	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Avenue Suffren		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 712

Building	Site Name	Site Code	Year / Season
113	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Avenue Suffren		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 714-716

Building	Site Name	Site Code	Year / Season
114	Port Louis	PL	2019
Ward number W3	Block number 84	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue L'Eglise		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Building	Site Name	Site Code	Year / Season
115	Port Louis	PL	2019
Ward number W3	Block number 84	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue L'Eglise		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 117-122

Building	Site Name	Site Code	Year / Season
116	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Replaced/Modern		Types of analysis Photo
Visibility Poor	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue L'Eglise		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 724-725

Building	Site Name	Site Code	Year / Season
117	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Suffren		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 726-731

Building	Site Name	Site Code	Year / Season
118	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Suffren		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 731-735

Building	Site Name	Site Code	Year / Season
119	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type Store	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Mgr. Gonin		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 736-739

Building	Site Name	Site Code	Year / Season
120	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Mgr. Gonin		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 740-743

Building	Site Name	Site Code	Year / Season
121	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
House	Original	Photo	
Visibility	Preservation Status		
Poor	Adequate		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Monseigneur Gonin	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment		Description	



Photo 744-746

Building	Site Name	Site Code	Year / Season
122	Port Louis	PL	2019
Ward number W3	Block number 86	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue Mgn. Gonin		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 747-750

Building	Site Name	Site Code	Year / Season
123	Port Louis	PL	2019
Ward number W4	Block number 218	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Louis Pasteur St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 751-753

Building	Site Name	Site Code	Year / Season
124	Port Louis	PL	2019
Ward number W4	Block number 218	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Inadequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Louis Pasteur St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 754

Building	Site Name	Site Code	Year / Season
125	Port Louis	PL	2019
Ward number W4	Block number 218	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
House	Disturbed/Restored	Photo	
Visibility	Preservation Status		
Good	Adequate		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Louis Pasteur St.	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 755-756

Building	Site Name	Site Code	Year / Season
126	Port Louis	PL	2019
Ward number W4	Block number 218	Elevation	Measure, Length
Building/Structure Type Warehouse	Building status Original		Types of analysis Photo
Visibility Very Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Sir. Virgil Naz St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 757-763

Building	Site Name	Site Code	Year / Season
127	Port Louis	PL	2019
Ward number W3	Block number 87	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Store	Original	Photo	
Visibility	Preservation Status		
Good	Good		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Rue L'Eglise	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 99-103

Building	Site Name	Site Code	Year / Season
128	Port Louis	PL	2019
Ward number W3	Block number 85	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue L'Eglise		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 104-107

Building	Site Name	Site Code	Year / Season
129	Port Louis	PL	2019
Ward number W3	Block number 85	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
House	Original	Photo	
Visibility	Preservation Status		
Poor	Inadequate		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Mgr. Gonin	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 108-110

Sul cancello d'ingresso é presente la data 1938 ma verosimilmente non corrisponde alla data dell'edificio originale interamente in legno.

Building	Site Name	Site Code	Year / Season
130	Port Louis	PL	2019
Ward number W4	Block number 226	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Monseigneur Gonin		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



In the middle of the block 226
Photo 110-112, 140-146

Building	Site Name	Site Code	Year / Season
131	Port Louis	PL	2019
Ward number W4	Block number 227	Elevation	Measure, Length
Building/Structure Type Warehouse	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dr. Eugene Laurent Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 115-118

Building	Site Name	Site Code	Year / Season
132	Port Louis	PL	2019
Ward number W4	Block number 227	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
House	Disturbed/Restored	Photo	
Visibility	Preservation Status		
Poor	Adequate		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Labourdonnais Street	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 119-120

Building	Site Name	Site Code	Year / Season
133	Port Louis	PL	2019
Ward number W4	Block number 227	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Impasse 32		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 121-122

Building	Site Name	Site Code	Year / Season
134	Port Louis	PL	2019
Ward number W4	Block number 228	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Impasse 32		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 123-126

Building	Site Name	Site Code	Year / Season
135	Port Louis	PL	2019
Ward number W4	Block number 258	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dr. Eugene Laurent		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 127-130

Building	Site Name	Site Code	Year / Season
136	Port Louis	PL	2019
Ward number W4	Block number 258	Elevation	Measure, Length
Building/Structure Type To be defined	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Dr. Eugene Laurent		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 131-134

Building	Site Name	Site Code	Year / Season
137	Port Louis	PL	2019
Ward number W4	Block number 258	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address D'Estaing Street, inner block		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 135-136

Building	Site Name	Site Code	Year / Season
138	Port Louis	PL	2019
Ward number W4	Block number 258	Elevation	Measure, Length
Building/Structure Type House	Building status Disturbed/Restored		Types of analysis Photo
Visibility Medium	Preservation Status Very Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Monseigneur Gonin		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 137-139

Building	Site Name	Site Code	Year / Season
139	Port Louis	PL	2019
Ward number W4	Block number 258	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Monseigneur Gonin		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 147-150

Building	Site Name	Site Code	Year / Season
140	Port Louis	PL	2019
Ward number W4	Block number 258	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Labourdonnais Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 151-152

Building	Site Name	Site Code	Year / Season
141	Port Louis	PL	2019
Ward number W4	Block number 259	Elevation	Measure, Length
Building/Structure Type House	Building status Disturbed/Restored		Types of analysis Photo
Visibility Medium	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue L'Eglise, inner block		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 153-155

Building	Site Name	Site Code	Year / Season
142	Port Louis	PL	2019
Ward number W4	Block number 259	Elevation	Measure, Length
Building/Structure Type House	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Very Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue L'Eglise		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 156-157

Building	Site Name	Site Code	Year / Season
143	Port Louis	PL	2019
Ward number W4	Block number 259	Elevation	Measure, Length
Building/Structure Type House	Building status Disturbed/Restored		Types of analysis Photo
Visibility Good	Preservation Status Very Good		
Distinction Parameters	Bdg.Type		
Neighbourhood	Address Rue L'Eglise		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 158-161

Building	Site Name	Site Code	Year / Season
144	Port Louis	PL	2019
Ward number W4	Block number 259	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
House	Original	Photo	
Visibility	Preservation Status		
Good	Adequate		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Labourdonnais Street/Monseigneur	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description

Photo 162-165



Building	Site Name	Site Code	Year / Season
145	Port Louis	PL	2019
Ward number W4	Block number 260	Elevation	Measure, Length
Building/Structure Type	Building status	Types of analysis	
Warehouse	Original	Photo	
Visibility	Preservation Status		
Poor	Good		
Distinction Parameters	Bdg.Type		
Building technique			
Neighbourhood	Address		
	Labourdonnais Street	Construction Materials	
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 166-167

Building	Site Name	Site Code	Year / Season
146	Port Louis	PL	2019
Ward number W4	Block number 260	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Medium	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Pope Hennessy St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 168-173

Building	Site Name	Site Code	Year / Season
147	Port Louis	PL	2019
Ward number W4	Block number 260	Elevation	Measure, Length
Building/Structure Type House	Building status Disturbed/Restored		Types of analysis Photo
Visibility Medium	Preservation Status Good		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Pope Hennessy St.		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description

Photo 174-176



Building	Site Name	Site Code	Year / Season
148	Port Louis	PL	2019
Ward number W4	Block number 260	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Poor	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Pope Hennessy Street		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 177-178

Building	Site Name	Site Code	Year / Season
149	Port Louis	PL	2019
Ward number W4	Block number 260	Elevation	Measure, Length
Building/Structure Type House	Building status Original		Types of analysis Photo
Visibility Good	Preservation Status Adequate		
Distinction Parameters Building technique	Bdg.Type		
Neighbourhood	Address Rue L'Eglise		Construction Materials
Openings Notes			
Roof Material	Roof Type	Roof Notes	
Siding Material	Siding Notes		
Dating Elements	Proposed chronology		
Photo, Sketch or Audio Comment			Description



Photo 179-181